

Asbestos Inspection



Clinton County Bridge 19

Team Involvement:

- Aaron Davenport
- Matt Dorsch

Bridge 19 was inspected for asbestos containing materials. A location map and report indicating the methodology of the sampling, location of samples taken, type, amount, summary and conclusions of the laboratory analyses. The laboratory analyses were conducted by Micro Air, Inc.



Blackford County Bridge 96

Bridge 96 was inspected for asbestos containing materials. A location map and report indicating the methodology of the sampling, location of samples taken, type, amount, summary and conclusions of the laboratory analyses. The laboratory analyses were conducted by Micro Air, Inc.